








1~7





8~12




NO.		Designation	Pieces	NO.		Designation	Pieces
1			X1	7		 Ø8	X7
2			X1	8			X2
3	E		X1	9			X2
	F		X1	10	A ₁		X1
	G		X1		A ₂		X2
	H		X1		A ₃		X4
			X1		A ₄		X2
4		 ST4X35	X7	B ₁			X2
		 ST4X35	X7	B ₂			X2
5		 ST4X10	X7/X9	B ₃			X1
6			X7/X10/ X12/X13	B ₄			X1
				C ₁			X2
				C ₂			X2
				C ₃			X1
				C ₄			X4
				C ₅			X2
				C ₆			X1
				D		No handle	
						 Ø8 Ø3.2	


1.




2.




b
(E)




b
(F)




b
(G)





b
(H)




3.




C








4.




d







5.




6.







f










7.










NO.	Designation	Pieces	NO.	Designation	Pieces
1		X1	7.1		X1
			7.2		X1
			8	A 	X1
				B 	X1
2		X1		 $\phi 8$ $\phi 3.2$	
3	 $\phi 8$	X4			
4	 $\phi 8$ ST4X35	X4			
5		X5			
6	 $\phi 8$ ST4X10	X5			







1.




2.




b




3.





C



5.



d



8

OR

